

# INVESTIGATION REPORT [HIGH SEVERITY]

Ref ID: DEV-2024-0312 | Rev 01 | CONFIDENTIAL

Status: Audit Ready | Generated: 2024-10-13

Batch ID	BTC0048	Product	Paracetamol Tablets 500mg
Plant	Unit-III Hyderabad	Severity	HIGH

## AI Generated Summary

The investigation report for batch BTC0048 of Paracetamol Tablets 500mg at Unit-III Hyderabad highlights a deviation in the granulation process. The Inlet Air Temperature exceeded the upper limit of 70°C, reaching 74.8°C on 2024-10-12 at 08:00, and the Product Bed Temperature reached 78.2°C at 08:15. Equipment ID EQP\_GRAN\_01 was involved. LIMS results indicate a failure in the assay with a result of 2.3%, below the specification of 1.5%-3%. The batch is currently on HOLD as per the Deviation Report.

## 01. Incident Overview

BATCH NUMBER	INCIDENT DATE	DEVIATION TYPE	DEPARTMENT
BTC0048	2024-10-12	Temperature Deviation	Granulation

## 02. Detected Deviations

SIGNAL/EXCEPTION	DURATION	PEAK VALUE	LIMIT
Inlet Air Temperature	1 hour 15 minutes	74.8°C	70°C
Product Bed Temperature	1 hour 15 minutes	78.2°C	70°C

## 3. Executive Summary

Batch BTC0048 of Paracetamol Tablets 500mg at Unit-III Hyderabad experienced a deviation on 2024-10-12. The Inlet Air Temperature reached 74.8°C, exceeding the upper limit of 70°C, and the Product Bed Temperature reached 78.2°C. Equipment ID EQP\_GRAN\_01 was involved. LIMS results showed an assay failure with a result of 2.3%, below the specification range of 1.5%-3%. The batch is currently on HOLD.

## 4. Deviation Description

The first deviation was recorded on 2024-10-12 at 08:00 with the Inlet Air Temperature reaching 74.8°C. The operator ID was not recorded. The temperature progressively rose, with the Product Bed Temperature reaching 78.2°C at 08:15. Immediate actions included stopping the process and initiating an investigation as per the Deviation Report.

## 05. Root Cause Analysis

PROBABLE CAUSE	METHODOLOGY
Equipment ID EQP_GRAN_01 had a calibration overdue by 15 days. Investigation involved reviewing equipment logs, maintenance records, and calibration history.	The investigation involved reviewing equipment logs, maintenance records, and calibration history.
CONCLUSION	
The root cause was identified as overdue calibration of EQP_GRAN_01, with a thermocouple drift of +4°C. Maintenance Log WO-2024-0456.	

## 6. Scope of Review

The review focused on the granulation process parameters, equipment performance, and LIMS results for batch BTC0048.

## 7. Exceptions

The primary exceptions were the Inlet Air Temperature and Product Bed Temperature exceeding their respective upper limits.

## 8. CAPA

CAPA actions included recalibration of EQP\_GRAN\_01 (WO-2024-0456), replacement of the thermocouple, and requalification of the equipment. A requalification report was generated post-maintenance.

## 9. Impact Assessment

LIMS results indicate the product was impacted. The assay result of 2.3% is below the specification of 1.5%-3%, referencing OOS-2024-0098. The batch is on HOLD.

## 10. Conclusion

The batch BTC0048 is currently on HOLD. An OOS investigation (OOS-2024-0098) is ongoing due to assay failure. Equipment EQP\_GRAN\_01 has been recalibrated and returned to service.

## 11. Regulatory Compliance

Standard	Status
21 CFR Part 211	Non-Compliant

## Compliance Checklist

Standard	Description	Status
21 CFR Part 211	Current Good Manufacturing Practice for Finished Pharmaceuticals	X Fail

---

Evidence Coverage Score: 95% — High Confidence

AI Insight: The deviation was primarily due to equipment calibration issues, which have been addressed through CAPA actions. Continuous monitoring and timely calibration are recommended to prevent recurrence.